

Salem County Department of Health and Human Services
ENVIRONMENTAL DIVISION

110 Fifth Street, Suite 400 – Salem, New Jersey 08079

856-935-7510 ext. 8448 - 856-358-3857

Fax 856-935-8483



Information for Real Estate Agents
Amendments to NJAC 7:9A regarding Real Property Transfer Inspections

As of April 2, 2012, the new amendments to the Individual Subsurface Sewage Disposal Systems code (NJAC 7:9A), have been adopted. The Salem County Department of Health (SCHD) has created this information sheet for Real Estate Agents to highlight some of the changes in the code as it pertains to real property transfers. Check NJDEP's website for additional information not found in the informational sheet - http://www.nj.gov/dep/dwq/owmp_main.htm

The Real Property Transfer Inspection Highlights are as follows:

1. The rule requires that cesspools be replaced at the time of real property transfer. This requirement does not apply to wastewater disposal systems which by definition do not include cesspools. Seepage pit systems or older traditional septic systems that do not meet current standards are not required by the rule to be upgraded.
2. The rule does not specify who is responsible for necessary upgrades during a real property transfer (seller or buyer); this should be negotiated during the real property transfer process.
3. The adopted rules provide for delayed implementation for 60 days of the requirement to upgrade functioning cesspools at the time of a property transfer in order **to accommodate property transfers already in process.**
4. Under previous rules, and up until April 2, 2012, a property owner with an existing cesspool could (with a permit from the SCHD) add a septic tank in front of the cesspool. This effectively converts the cesspool to a seepage pit system and that seepage pit system would not be subject to the requirement to immediately upgrade. On April 2, 2012, any cesspool requiring repairs must be upgraded; there is no 60 day delay for this provision. **Addition of a septic tank in front of the cesspool will no longer be allowed.**
5. The rule establishes a protocol for inspecting onsite systems during real property transfer. The rule does not mandate its use nor does it require an upgrade to the system as a result of that inspection. This portion of the rule provides buyers and sellers with information based on a comprehensive evaluation of the system and can assist in negotiations for the transaction. Unsatisfactory results, **unless they indicate the system is malfunctioning**, do not require that anything be done immediately (although work done on the system must be properly permitted locally).
6. If something is observed during the inspection that is indicative of a malfunctioning condition, **it must be reported to the Salem County Health Department and addressed as a report of a malfunctioning system.** Since 1990, property owners with a malfunctioning system had an obligation to report the malfunction to SCHD immediately. The inspection report is a new way of gathering and reporting information characterizing a malfunctioning system. A copy of the report must be sent to the local administrative authority in order to meet the requirements of the inspection protocol.
7. Septic System Inspectors (usually septic installers), performing real property transfer inspections shall describe the visible observations made during the inspection. **Only the health department and the NJDEP can classify a septic system as "malfunctioning", "failure", or "non-compliant" in accordance with NJAC 7:9A-3.4(d).**